




# HP Pavilion G6-2249wm screen Replacement

I'm going to remove and replace a broken screen

Written By: hunter



## INTRODUCTION

I'm going to replace the broken screen because my dad is not the best with technology and punched the screen.


---



## PARTS:

- [15.6" PC Laptop LCD N156B6-L0B](#) (1)
-

## Step 1 — Battery removal



- Make sure the computer is shut off.
- When you know that is shut off you may remove the battery


## Step 2 — Begin screen removal



- Remove the little pieces of black sticky tape covering the screws that need to be removed in each lower corner



### Step 3 — screw removal




- After the little black sticky tape is removed the two little screws at the lower corners of the screen need to be removed (place the screws on a little piece of tape).

### Step 4 — screen cover removal



- After removing the screws, pop out the plastic protector (can be done with your fingers).
- Start at one corner and run your finger under the plastic and it will pop out.

## Step 5 — screen screw removal



- On each side of the screen there are two little screws, one on top and one on bottom.
- All four of the screws need to be removed (place the screws on a little piece of tape so they won't be lost).


## Step 6 — screen removal



- Once the screws are out, remove the screen and lay it on your keyboard.




## Step 7 — digital attachment removal



- Once the screen is laying down you will see a connector on the back of it.
- Pull the sticker off which pulls the connector with it.

## Step 8 — Reconnecting the screen



- After the new screen has arrived, reconnect the little connector strip.

## Step 9 — Replacing the screws



- After the connector has been connected place the screen back into its place.
- Once the screen is in place put in the four little screws that go in each corner of the screen.

## Step 10 — black cover placement



- After the screen is screwed in place the black plastic cover back over the screen.
- Once the black over is in place start clicking the clips back into place by just pressing with your fingers.




## Step 11 — Screwing the cover in place



- After the black cover is in place start to put the two little screws back in the two button corners


## Step 12 — Sticker placement



- After the screws are in place the little black sticker over the screws.




## Step 13 — Placing the battery



- After the screen is in and everything is tight and in place you may put the battery back in.

## Step 14 — Turning on the computer



- Once the battery is in place you may turn it on and watch your screen come back to life.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-19 09:52:42 AM.